

BUILDING REHABILITATION

3. WATERPROOFINGS, FLAT ROOFS, DOORS AND WINDOWS

Lajos Gábor, Takács PhD

associate professor

BME Department of Building Constructions



email: ltakacs@epsz.bme.hu



WATERPROOFING FAILURES OF SUBSTRUCTURES





MOISTURE EXPOSURES IN SOIL – SOIL VAPOUR



- Vapour between the soil particles
- Comes from the evaporation of the subsoil water
- Condensates of the surface of the subconstructions:
subsoil moisture





MOISTURE EXPOSURES IN SOIL – SOIL VAPOUR



- Water on the surface of the particles
- No hydrostatic pressure
- Capillarity
 - Abrasive particle subsoil – 2-3 cm
 - in adherent subsoil – clay – even 300 m!



MOISTURE EXPOSURES IN SOIL – SOIL VAPOUR



- Gaps between the soil particles filled completely with subsoil water
- Hydraulic pressure (depends on the level difference between the floor and the water table)
- Uplift hazard





WATERPROOFINGS – TYPICAL MISTAKES

- Design and construction failures
- Mechanical damage
- Lack of performance based design – inadequate waterproofing for the given exposure (f.i. 1 layer of bituminous sheet against subsoil water)
- Discontinuous waterproofing – missing parts or inadequate joints



PIPE PENETRATIONS OF WATERPROOFINGS – SLEEVE + LINK-SEAL




PIPE PENETRATIONS OF WATERPROOFINGS – SLEEVE + LINK-SEAL




FAILURE: MISSING SLEEVE + LINK-SEAL



FAILURE: MISSING SLEEVE + LINK-SEAL



INADEQUATE SOIL BACKFILL POOR COMPRESSING




FLAT ROOF FAILURES




FLAT ROOF ALTERNATIVES


normal




inverted



DUO



Double shell



$$t_i \geq 24^{\circ}\text{C}$$

$$j_i \geq 75\%$$





FLAT ROOFS – INCLINATION

How to provide inclination:

- with the loadbearing structure
- screed, lightweight screed
- special thermal insulation

Minimum 2 ‰ (over lightweight structures, minimum 3 ‰)

Pointwise drainage – linear drainage is not allowed in Hungary!




FLAT ROOFS – INCLINATION

How to provide inclination:

- with the loadbearing structure
- screed, lightweight screed
- special thermal insulation

Minimum 2 % (over lightweight structures, minimum 3 %)

Pointwise drainage – linear drainage is not allowed in Hungary!




FLAT ROOFS – INCLINATION



Csarnok lejtésképe

szigetelés aljzatának minimális lejtése:
 - hőszigetelt aljzat esetén 2,5%
 - trapézlemez esetén 3% (lehajlás miatt)



FLAT ROOFS – TYPICAL MISTAKES

- Ageing – especially at bituminous waterproofings (UV protection)
- Inadequate vapour barrier – condensation under the bottom level of the waterproofing
- Inadequate thermal insulation
- Inadequate inclination – water accumulation – ageing, plants
- Blocked rainwater outlets (gullies)
- Inadequate protection against root acid




FLAT ROOFS – INADEQUATE INCLINATION



GULLY ALTERNATIVES



GULLY ALTERNATIVES – SYPHONIC ROOF DRAINAGE



FLAT ROOFS – LACK OF VAPOUR BARRIER CANNOT BE REPLACED WITH TECHNOLOGYCAL FOIL!



FLAT ROOFS – THERMAL INSULATION BOARD SHRINKING





FLAT ROOFS – FAILURE OF AUXILIARY STRUCTURES



FLAT ROOFS – IMPROPER CRAFTMANSHIP




FLAT ROOF FAILURES



EXTERNAL DOORS, WINDOWS AND THEIR TYPICAL FAILURES



EXTERNAL DOORS AND WINDOWS - EXPOSURES





1. temperature difference/swing
2. vapour pressure difference
3. wind
4. solar radiation
5. rain
6. noise
7. dust, pollution



EXTERNAL DOORS AND WINDOWS – PERFORMANCE CRITERIAS

<ul style="list-style-type: none"> ● resistance to wind load ● resistant to snow load ● reaction-to-fire classification ● weatherproofness ● hygieny, health and safety ● mechanical durability ● loadbearing capacity and security ● width and height ● acoustics (sound insulation) ● thermal insulation criteria ● radiation (daylight factor– g) ● air permeability ● durability (general and determined) ● operating force ● mechanical durability (strenght) ● ventilation (open ratio) ● (bullet- and explosion proofness) ● resistace to repeated opening and closing 	<p>frame A,B,C, surface pressure: 1,2,3,4,5,E A, B, C A1, A2, B, C, D, E, F 1A, 2A... ...9A, E related standard ball 200, 300, 450, 700, 950 mm declared value</p>
<ul style="list-style-type: none"> ● behaviour between different climates ● burglary resistance 	<p>declared value declared value (1,6-2,0 W/m2K) declared value class 1, 2, 3, 4</p> <p>class 1, 2 1, 2, 3, 4 declared value (cv factor, characteristics, etc.) FB1- FB7, FSG; EPR1-4, EXR1-5</p> <p>5000, 10 000, 20 000 times in preparation... class 1, 2, 3, 4, 5, 6</p>

ENERGY BALANCE OF DOUBLE GLASING




energy balance of the glass

$T_{\text{short wave}} > T_{\text{long wave}} \rightarrow$
 \rightarrow glass house effect
 (overheating)

rolled glass – (was) cheap
 float glass – high quality

Glass	U_g
single layer	5,8 W/m ² K
double (4-12-4)	2,8 W/m ² K
triple (4-12-4-12)	2,1 W/m ² K

ENERGY BALANCE OF DOUBLE GLASING




energy balance of the glass

$T_{\text{short wave}} > T_{\text{long wave}} \rightarrow$
 \rightarrow glass house effect
 (overheating)


rolled glass – (was) cheap
 float glass – high quality

edge of the double glass




Glass	U_g
single layer	5,8 W/m ² K
double (4-12-4)	2,8 W/m ² K
triple (4-12-4-12)	2,1 W/m ² K


COATED GLASSES, TRIPLE GLASSES, MULTIFUNCTIONAL GLASS




double
4 - 16 - 4




low-emission
coating



Solar coating




multifunctional
coating



triple glass pane with argon

4 - 10 - 4 - 10 - 4	0,8 W/m²K
4 - 12 - 4 - 12 - 4	0,7 W/m²K
4 - 14 - 4 - 14 - 4	0,6 W/m²K
4 - 16 - 4 - 16 - 4	0,6 W/m²K *

LOW EMISSION (LOW-E) GLASS



winter energy balance
of glass with no coating

radiation
67%


with no coating

In the gap $U(W/m^2K)$

air 2,78

argon 2,61

convection, thermal
conduction
33%



winter energy balance of
glass with low-e coating

low-e coating


in the gap $U(W/m^2K)$

air 1,8

argon 1,3

cripton 1,1

radiation







construction of single layer
low-e coating

thickness: 0,2 μ




ALUMINIUM VS. PLASTIC SPACERS OF TRIPLE GLASING




ALUMINIUM VS. PLASTIC SPACERS OF TRIPLE GLASING




DOORS, WINDOWS - INSTALLATION




sealing inside and outside




sealing + foil




foil inside and outside



behind thermal insulation




In the middle of the wall




at the thermal insulation




DOORS, WINDOWS - INSTALLATION




precipitation
pushed up by wind




window flashing



artificial stone



waterproofing




balcony




DOOR, WINDOWS - INSTALLATION

Installation of an up-to-date laminated timber window into a wall with external thermal insulation composite system (ETICS), horizontal section



Installation of an up-to-date laminated timber window with frame extension into a wall with external thermal insulation composite system (ETICS), parapet detail



DOOR, WINDOWS – INSTALLATION



DOOR, WINDOWS - INSTALLATION



EXTERNAL DOORS AND WINDOWS

Important features:

- Moving parts – sash
- Joints

Typical problems:

- Missing lintel – deformation
- Improper installation – missing external wind-and raintight foil, missing vapour barrier
- Thermal bridge – poor thermal insulation around the door or window
- Mechanical failure – lack of maintenance
- Failure of finishing (especially at timber windows)
- Missing connection to the waterproofing – water penetration



EXTERNAL DOORS AND WINDOWS

Important features:

- Moving parts – sash
- Joints

Typical problems:


- Missing lintel – deformation
- Improper installation – missing external wind-and raintight foil, missing vapour barrier
- Thermal bridge – poor thermal insulation around the door or window
- Mechanical failure – lack of maintenance
- Failure of finishing (especially at timber windows)
- Missing connection to the waterproofing – water penetration




DEWATERING PROBLEMS



EXTERNAL DOOR CONNECTION TO THE WATERPROOFING




EXTERNAL DOOR CONNECTION TO THE WATERPROOFING



EXTERNAL DOOR CONNECTION TO THE WATERPROOFING




SKYLIGHT WINDOWS – CONNECTION OF THE UNDERLAYER FOIL



SKYLIGHT WINDOWS – CONNECTION OF THE UNDERLAYER FOIL

1. Ribbed lead sheet bottom part
2. side pieces with plastic foam sealing strip
3. top gutter strips with plastic foam sealing
4. tile underlay
5. plastic foam sealing
6. gutter strip
7. vapour barrier
8. underlay foil



Window frame is fitted to top surface of rafters. The two foil layers are connected to the frame around its entire perimeter.




SKYLIGHT WINDOWS – INSTALLATION



↑protection of bottom edge with ribbed lead sheet

gutter strips around the window frame →



SKYLIGHT WINDOWS – VAPOUR BARRIER - CONTINUITY



SKYLIGHT WINDOWS – THERMAL INSULATION - CONTINUITY



SKYLIGHT WINDOWS – IMPROPER INSTALLATION




SKYLIGHT WINDOWS – IMPROPER INSTALLATION

Vapour condensation „open sky”
problem (overcooling problem) – must
be compensated with local heating unit!



TRADITIONAL DOUBLE SASH WINDOW AND ITS RECONSTRUCTION




TRADITIONAL DOUBLE SASH WINDOW - FAILURES




BUILDING REHABILITATION

III. INTRODUCTION TO BUILDING DIAGNOSTICS – FLAT ROOFS, FINISHINGS




BUILDING REHABILITATION

III. INTRODUCTION TO BUILDING DIAGNOSTICS – FLAT ROOFS, FINISHINGS





BUILDING REHABILITATION

III. INTRODUCTION TO BUILDING DIAGNOSTICS – FLAT ROOFS, FINISHINGS



REPLACEMENT OF TRADITIONAL DOUBLE SASH WINDOW TO SINGLE SASH UP-TO-DATE CONSTRUCTION INCREASING THERMAL BRIDGE EFFECT



INTERNAL DOORS



FAILURES OF INTERNAL DOORS

No external exposures (wind, rain)

Mechanical exposures – especially in public buildings

Performance criterias:

- Operating forces (accessibility)
- Repeated opening and closing cycles
- Behavior between different climatic conditions
- Airborne sound insulation performance
- Durability (mechanical resistance)

Typical problems

- Missing lintel – deformation
- Improper installation



IMPROPER INSTALLATION



Performance criterias:

- Operating forces (accessibility)
- Repeated opening and closing cycles
- Behavior between different climatic conditions
- Airborne sound insulation performance
- Durability (mechanical resistance)

Typical problems

- Missing lintel – deformation
- Improper installation




FAILURES OF INTERNAL DOORS




FLOOR STRUCTURES, FLOOR COVERINGS




FLOOR STRUCTURE ALTERNATIVES



Contact floor
(hard, soft)



elastic




Floating floor



FLOATING FLOOR STRUCTURE

Layers are:

- Floor covering
- Adhesive
- Self-levelling layer
- Screed
- Technological layer
- Acoustic insulation
- Installation layer (electricity, HVAC)
- Floor slab



HVAC AND ELECTRIC INSTALLATIONS IN THE FLOOR LAYERS



HVAC AND ELECTRIC INSTALLATIONS IN THE FLOOR LAYERS ...



HVAC AND ELECTRIC INSTALLATIONS IN THE FLOOR LAYERS ...



Typical failures are:

- Frost damage
- Mechanical damage
- Improper anti-slippery performance

FLOOR COVERING FAILURES

